

2018 AASHTO SCOBS Bridge Meeting T-1 Bridge Security & Hazards

Case Studies Rehabilitation from extreme events

Artur D'Andrea



Presentation Topics

1. SAMPLE OF MULTI-HAZARD RESPONSES
2. EXAMPLES OF RESPONSES, TEMPORARY AND PERMANENT
3. RISK AND SOLUTIONS
4. FUNDING
5. OWNERS' FLEXIBILITY
6. RECOVERY PERIOD, "TIME ELEMENT"
7. RESTORATION COSTS

RESPONSES TO MULTI-HAZARD EVENTS ARE:

1. DEPENDENT ON THE SIZE OF THE IMPACTS
2. LEVEL OF NATIONAL ATTENTION
3. OWNERS ABILITY TO MOBILIZE ADEQUATE RESOURCES
4. OWNERS EXPERIENCE WITH RECOVERY FROM EXTREME EVENTS

MAJOR EVENTS CAUSE SHORTAGES OF AVAILABLE
RESOURCES AS VARIOUS PRIVATE AND PUBLIC ENTITIES
COMPETE FOR THE SAME EQUIPMENT AND CAPABLE PEOPLE.

AT THE SAME TIME NORMAL ACCESS ROUTES, POWER,
COMMUNICATIONS BECOME COMPROMISED, THUS
WORKING WITH SCARCITY BECOMES THE NORM

FOR EACH DAMAGED ASSET THE BASIC DECISION

REPAIR

OR

REPLACE

TYPICAL APPROACH DOT DEPLOYED DURING EXTREME EVENT

AN EMERGENCY MULTI-AGENCY TEAM IS DEPLOYED AND HOUSED AT SELECTED LOCATION. DOT'S TEAM MEMBER MAKES AVAILABLE RESOURCES IT CAN PROVIDE AT AFFECTED SITES

CRITICAL PROBLEMS AND INTERRUPTIONS ARE IDENTIFIED, CREWS ARE DISPATCHED FOR REPAIRS AND RESTORE SERVICE

SOON AFTER PRE-SELECTED TEAMS EVALUATE THE REPAIRS RECOMMEND ADDITIONAL WORK OR RELACEMENT AS NECESSARY

March 2016 Flood







U.S. Department
of Transportation
Federal Highway
Administration

DETAILED DAMAGE INSPECTION REPORT

(Title 23, Federal-aid Highways)

Report Number

LA-2016-1-013-

Sheet

1 of 1

Location (Name of Road and Milepost)

I-20, C.S. 451-04, Logmile 1.54

FHWA Disaster Number

March 2016 Flood Event

Inspection Date

3/20/2016

Description of Damage

S.N. 040704510401542, R.N. 011750

Drift accumulation on northwest corner of bridge. Bridges are adjacent to recent clear cut. Cast-in-place revetment failure and wash out on east end between eastbound and westbound bridges ~ approximately 100 ft x 25 ft.

Artur D'Andrea, Mark Bucci, James Melton

Federal-aid Route Number

I-20

State

LA

County

Bienville

Cost Estimate

Description of Work to Date (Equipment, Labor, and Materials)	Unit	Unit Price	Quantity	Cost	
				Completed	Remaining
Labor (divided amongst three I-20 sites)	EA	8713.05	.33	2904.35	
Equipment (divided amongst three I-20 sites)	EA	10011.40	.33	3337.14	
Materials (divided amongst three I-20 sites)	EA	4272	.33	1424	

GRILLETTE, KYLE	P00173641	03/10/2016	EA03 - EXC-PAY OT @ 1.5 RATE	13.00	\$ 422.16
LEE, DOUGLAS	P00177414	03/10/2016	EA03 - EXC-PAY OT @ 1.5 RATE	11.00	\$ 303.60
SMITH, DANIEL	P00256970	03/10/2016	EA03 - EXC-PAY OT @ 1.5 RATE	14.00	\$ 318.79
RASBURY, WILLIAM	P00270011	03/10/2016	EA03 - EXC-PAY OT @ 1.5 RATE	13.00	\$ 254.82
HAVARD, TIMOTHY	P00275257	03/10/2016	EA03 - EXC-PAY OT @ 1.5 RATE	13.00	\$ 245.02
WRIGHT, DUSTIN	P00277261	03/10/2016	EA03 - EXC-PAY OT @ 1.5 RATE	13.00	\$ 298.77


Equipment:

Equipment #	Equipment Class Code	Operator	Work Date	Total Hrs	Mileage	Total Cost
124001	Truck, Pickup - 1 ton - HP	WILLIAM J RASBURY	03/10/2016	13.00	118	\$ 260.00
137172	Truck, Pickup - 1 ton - HP	KYLE L GRILLETTE	03/10/2016	13.00		\$ 260.00
137235	Truck, Pickup - 1 ton - HP	DANIEL C SMITH	03/10/2016	14.00		\$ 280.00
159515	Truck, Tractor - 50000 lb - to 400HP	ALBERT T MOREAU	03/10/2016	14.00		\$ 770.00




CASE 1

- TIME, EARLY 1980'S
- LOCATION I-59, PEARL RIVER BRIDGE MAIN SPANS
- CONDITION, MULTI FLOOD EVENTS AND ABANDONED BARGE CAUSED HEAVY SCOUR AND BRIDGE INSTABILITY



I-59 Bridges over the Pearl River

Affected bridges



Louisiana
View - Jun 2014

AFFECTED BRIDGE ELEMENTS







[illegible]

MIN.HORIZ CL= 130'


5-54" PCPILES





ORIGINAL
GROUND LINE

GROUND LINE
AFTER OBSERVED
SCOUR



USGS 02492600 Pearl River at Pearl River, LA

Rank	Year	Date	gage height, ft	Stream Flow (cfs)
1	1983	Apr. 09, 1983	21.05	230,000
2	2016	Mar. 14, 2016	20.58	206,000
3	1874	1874	20.2	198,000
4	1900	Apr. 19, 1900	19.7	179,000
5	1980	Apr. 02, 1980	19.75	173,800
6	1979	Apr. 26, 1979	19.25	155,000

St. Tammany Parish,
Louisiana
Hydrologic Unit Code
03180004
Latitude 30°23'06",
Longitude 89°44'12"
NAD27
Drainage area
8,494.00 square miles
Gage datum -0.05 feet
above NGVD29

DESCRIPTION DLST. 62 WEST PEARL Sheet No. 2 of 2
SOUTH BOUND RDWY. I-59
STR. NO. 4530105242 Date 8-7-81

25	5 $\frac{5}{8}$ "	5 $\frac{7}{8}$ "	BOTH SIDES WIDE OPEN
24	2 $\frac{5}{16}$ "	2 $\frac{1}{4}$ "	CRACK IN PEDESTAL @ BT. #24
23	2 $\frac{1}{4}$ "	2 $\frac{3}{4}$ "	EAST SIDE HAS WORSENERD SINCE LAST REPORT. BASE PLATE NOT SETTING LEVEL.
22	1 $\frac{5}{8}$ "	1 $\frac{5}{8}$ "	BOTH SIDES CLOSED TIGHT
21	3"	2 $\frac{3}{4}$ "	

IN AREAS WHERE STEPPED
RISERS ARE SPALLED
THEY ARE TO BE
CLEANED AND
REPAIRED WITH
EPOXY GROUT.


SHEET 1 OF 5
(TYPICAL DETAILS)

REPAIRS

TYP. ANCH. FIXED BRG.
1- HEAVY HEX NUT
1- CUT WASHER

TYP. ANCH. EXP. BRG.
2- HEAVY HEX NUTS
1- WASHER

CUT & WELD NEW
SECTION



WEST PEARL RIVER I-59 ST. TAMMANY

ESTIMATED QUANTITIES


BRG. PAD	7x20x2	16	EA.
BRG. PAD	9x21x1	16	EA.
BRG. PAD	7x22x2 7/16	16	EA.
BRG. PAD	9x22x3 1/16	8	EA.
STEEL (A-36)		6553	LBS.


NOTE: AFTER TOP PLATES ARE WELDED TO FLANGE & IN PLACE, ENTIRE BRG. IS TO BE SAND BLASTED & PAINTED WITH AN APPROVED PAINT SYSTEM. (TYPICAL.)

UP STA.

BENT # 23

SHEET 3 OF 5





I 59
 South Bound Rdwy
 Bridge Number — 4530105.242
 ST TAMMANY PARISH
 DISTRICT 62

JOINT OPENING

BENT Number	WEST B LT GUTTER LINE	EAST R GUTTER LINE
23	2" $\frac{1}{4}$ " *	2 $\frac{1}{2}$ " $\frac{3}{4}$ " *
24	2" $\frac{1}{4}$ " *	2" 1" *
25	1 $\frac{3}{4}$ " 4 $\frac{3}{8}$ " *	2" 5 $\frac{3}{8}$ " *
26	$\frac{15}{16}$ "	OK * $\frac{3}{4}$ "

* Red Notes
 Before Repairs
 12-14-81

NOTE: JOINT OPENING MEASURED
 AT GUTTER LINE ON SLIDING
 PLATE JOINTS.

BY WTL DATE 6-15-82
BY WTL RA DATE 6/16/82
BY _____ DATE _____
BY _____ DATE _____

MEMORANDUM TO:

MR. JACK R. REID
DIRECTOR OF PRECONSTRUCTION

*ARE ALL EXISTING CONDITIONS & CHANGES
TO ORIGINAL AS BUILT PLANS SHOWN ON THE
BRIDGE INSP. REPORT PARTICULAR EXIST BEARINGS
OF EACH GIRDER ON EACH END— LUBERITE PLATE LOCATION/
JOINT MEAS. AS BRIDGE DESIGN WILL NEED FOR PLAN PREP.*

The Plan-in-Hand Inspection on the above captioned project was made on June 4, 1982. Personnel making this inspection are listed on the attached Plan-in-Hand Memorandum Review.

1. Bents No. 21 thru 26 to be moved to correct position. This will be determined from bridge inspection reports and by using measurements from bents no. 21 and 26.

*BRIDGE INSP. SHOULD BE
COMP. ENOUGH TO SHOW
LOCATION OF BENTS—JOINT
EACH BENT MEAS CORR TO
DIST FOR TEMP.*

2. Top 20' of piles to be encased if jetting is used.

*SHOULD SHOW EACH
GIRDER BEARING WITH LOCATION
OF LUBERITE PLATE ON
ALL BENTS ON BOTH STR.*

3. Existing fender system to be removed.

*→ KEN-MAURICE-NATHAN
IN REPORT (INSP.) DO NOT*

4. All bearing plates, shoes and anchor bolts to be corrected on bents 21 thru 26.

*SHOW THAT IT SHOULD BE
ACCOMPLISHED IMMEDIATELY SO
CORRECTIONS—REPAIRS ACCOMPLISHED
CORRECTLY— ALSO SEE LETTER
& SKETCHES DATED
APR. 29, 1981*

5. It is recommended that our Legal Section take whatever action is necessary to have a sunken barge removed from the channel on the upstream side of the bridge.

6. CAPS SHOULD BE DESIGNED CONTR. TO FACILITATE FUTURE RECD DECK
& SHOULDER WIDTHS WHEN LIGHT WEIGHT DECKS HAVE TO BE REPLACED

EUGENE P. WAGUESPACK
DOTD CHIEF CONSTRUCTION ENGINEER

*& MEET PRESENT DAY
DESIGN REQ.*

T. W. Bergeron

T. W. BERGERON
BRIDGE CONSTRUCTION ENGINEER

1. SCOUR CAUSING HEAVY LOSS OF PILE
PENETRATION AT BENTS 23 AND BENTS 24

2. EXCESSIVE MOVEMENTS AT THEIR TOPS, 3" TO 4"

3. BTS23 & 24 WERE TIED OFF TO PREVENT
FURTHER MOVEMENT

4. THEIR REPLACEMENT WAS BEING PLANNED

5. UNACCEPTABLE LONGITUDINAL MOVEMENT WAS
SET AT FIVE INCHES MAXIMUM

6. TILTMETER WAS INSTALLED

Mr. Lynn R. Lane

Engineering Department Head
Flight Systems
Phoenix, Arizona 85027

Mr. Knapp
Please advise me
Lab
advised G. H. G.
02/1/83 that 5" would
be max. without prompt
action. N/A
Tilt Sensor Installation
West Pearl River Bridges
Interstate 59
St. Tammany Parish, LA
Structures No. 453 01 0524 1
453 01 0524 2
453-01-25

Dear Mr. Lane:

This is to request a proposal to install a Tilt Sensor Alignment
Monitor System on the above referenced bridges.

The attached plan sheets show that bents 23 and 24 of each bridge
have lost a significant amount of penetration due to scour. These bents
are somewhat slender and have experienced excessive movement of 3" to 4"


Plans are being prepared to replace these bents. They are now tied
off to prevent further excessive movement. An installation to monitor the
position of the bents and warn of any movement beyond a predetermined amount
would make the situation substantially safer.

We understand that systems are available which provide continuous
monitoring with intermittent recording. Additionally, a warning device can
be triggered when a predetermined degree of tilt occurs. The warning
threshold can be set from 1 to 20 arc minutes. Is this threshold pre-set
and fixed at the factory or is it user adjustable?

PLAN SUBS E. PAPER - I-59
SEND WITH REQ FOR PROVISION TO
MONITOR

SPERRY

TILT
+
sensor



The low cost, reliable leveling monitor.

Sperry's Tilt Sensor simply, economically and *continuously* monitors vertical and/or horizontal alignment of the structure on which it is mounted.

Proven hardware

The heart of the Tilt Sensor is a miniature Electrolytic Gravity Sensor used as a leveling device in highly accurate aircraft and marine gyroscope systems. Advanced electronics and the gravity sensor are mounted in a rugged, lightweight sealed housing.

Versatile

The Tilt Sensor can be preset to give a warning signal of deviation. The warning threshold may be set as low as 1 minute of arc. Various warning devices, including strobe lights, horns and radio links, may interface with the Tilt Sensor, or it may be hard-wired to a central location. With a recorder, it can provide a permanent log of the actual alignment angle.

The extremely low operating power of the Tilt Sensor allows months of battery use. It can also be powered from a ± 6 VDC supply.

Wide application range

The many potential uses of Tilt Sensors include monitoring of:

- Building structural integrity during construction, and collection of movement data during building life.


- Roofs, floors and ramps of public assem-

Mr. Doyle and our project personnel were informed that with the heavy loads in Span No. 22 and the removal of the restraining properties of Span No. 23, the Bent No. 23 would tend to try to move toward the river. Because of this the bearing of Span No. 22 on both Bents No. 22 and 23 should be checked to ensure proper bearing and to be sure that the fixed bearing on Bent No. 22 were fully functioning and that the anchor bolts were not sheared or the embedment concrete cracked. If there are problems with the restraints on Bent No. 22 then another restraining method should be devised.

SUNKEN
BARGE



BENT 23 AND 24 NB AND
SB



1. Spans removed


2. Bent cap demolished

3. Existing piles driven down 30'

4. New cap/footing poured

5. New columns built


6. Spans placed back on top of the new cap




ADDED BRIDGE ELEMENTS




BENT NO 24 RT






HLINE C



GRID SCALE 2'x2'
WEST PEARL
I-10

23

ED: OPERATION I



ED:

RECEIPT
 Received on State Project No. 453-01-25
 Project No. BHI-59-1(017)005
 BRIDGES (REHABILITATION) _____ Hwy. _____
 _____ Parish _____
 _____ Length - - - - Miles _____
 E EXISTING BRIDGES _____


STATE OF LOUISIANA
 DEPARTMENT OF TRANSPORTATION
 AND DEVELOPMENT

Date February 29, 1984 Bids received up to
 Room 431, Headquarters Administration Buildi
 To be opened and read at 10:00 A.M. of the sam
 in the Auditorium.
 Extensions checked by bn
 Checked against proposals by AEB/226

NAME OF BIDDER			
ITEM NO.	QUANTITY	UNIT	ITEM
202(2)(I)	Lump	Lump	Removal of Reinforced Concrete
713(1)	Lump	Lump	Temporary Signs & Barricades
725(1)	2,610.2	Lin.Ft.	Temporary Detour Roads
727(1)	Lump	Lump	Mobilization
805(1)(F)	775.96	Cu.Yd.	Class A Concrete(Bents)
805(3)	873.64	Cu.Yd.	Class AA Concrete
805(9)	177.0	Lin.Ft.	Expansion Joint Seal
806(1)	344,414	Pound	Deformed Reinforcing Steel
807(6)	Lump	Lump	Structural Metalwork
S-101	100	Each	Temp.Prec.Barrier(Hauling from N.LA)
S-102	170	Each	Temp.Prec.Barrier(Hauling from S.LA)
S-103	Lump	Lump	Rem.& Restor.of Exist.Struc.Steel
S-104	Lump	Lump	Removal of Sunken Barge
S-105	59.0	Lin.Ft.	Strip Seal(4")
S-106	20	Each	Excavation & Concrete Fill in Piles
S-107	20	Each	Redriving of Existing 54"Ø Piles
S-108	2,696	Each	Shear Connector Bar Extension
S-109	Lump	Lump	Rem.& Install.of Exist.Aluminum Hand R
TOTAL AMOUNT OF EACH CONTRACTOR'S LOW BID:			
CERTIFIED CORRECT			
PROJECT CONTROL ENGINEER			

Low bidder, selected pay items
 Concrete Cap Demolition (4)= \$165,000
 Mobilization \$100,000
 Interstate CrossOver Detour \$399,360
 Removal and Reinstallation
 4 Spans \$300,000
 And Girder Restoration
 Re-driving all 54" piles \$67,000
 Total \$1,752,494

- AUGUST 2016 FLOOD EVENT





By U.S. Department of Agriculture -

LA 10: AMITE RIVER SCOUR REPAIR

state_route_number

LA0010

AMITE RIVER @ DARLINGTON


i109_pct_adt_truck 23

i29_adt 002300

Year Completed 1963

Dimensions=605'x28'

- 1) 22.54 ft on 08/13/2016
- (2) 22.05 ft on 01/25/1990
- (3) 21.76 ft on 04/22/1977
- (4) 21.17 ft on 04/13/1955
- (5) 20.29 ft on 04/07/1983
- (6) 20.20 ft on 01/07/1950
- (7) 20.19 ft on 03/25/1973
- (8) 20.17 ft on 01/28/1994
- (9) 19.69 ft on 03/18/1961
- (10) 19.59 ft on 03/28/1980





LA 10 Amite River

Channel Migration

Photos from Atlas Louisiana GIS & Google Earth




LA 10 Amite River

Channel Migration: December 2015 Aerial




LA 10 Amite River

August Flood Photos



<http://www1.wbrz.com/videos/big-rig-washed-away-by-flooding-on-hwy-10>





$R = 19.28'$
 $D = 297^{\circ}15'14.36''$
 $\Delta = 60^{\circ}09'18.49''$ LT.
 $L = 20.24'$
 $T = 11.16'$

C4: PI STA. = 2+26.26
 $R = 31.21'$
 $D = 183^{\circ}34'36.82''$
 $\Delta = 53^{\circ}34'26.33''$ RT.
 $L = 29.18'$
 $T = 15.76'$

C5: PI STA. = 3+21.50
 $R = 100.25'$
 $D = 57^{\circ}09'13.63''$
 $\Delta = 35^{\circ}06'23.40''$ RT.
 $L = 61.42'$
 $T = 31.71'$

C6: PI STA. = 4+09.33
 $R = 251.57'$
 $D = 22^{\circ}46'31.35''$
 $\Delta = 11^{\circ}57'48.20''$ RT.
 $L = 52.53'$
 $T = 26.36'$

NOTES:

1. FOR CROSS SECTIONS SEE SHEET
2. DEPRESS RIPRAP AT THE LOCATION OF EXISTING 15" RCP SO AS NOT TO
3. PLACE RIPRAP AT 2 1/2:1 SLOPE. SEE CROSS SECTIONS.
4. IMPROVE EXISTING RIPRAP TO MAINTAIN REQUIRED 2 1/2:1 SLOPE.
5. SEE GENERAL NOTES SHEET 101 FOR ADDITIONAL INFORMATION ON JOINTS.




11/4/16



FINAL PLANS

IP_PWP:d0600586\104_Cross_Sections.dgn

11/3/2016 16:11





NOTES

1. DRESS GROUND WITH GEOTEXTILE FABRIC AS SHOWN BEFORE PLACING BORROW AND RIPRAP. WRAP GEOTEXTILE FABRIC AROUND TOE AS SHOWN IN DETAIL "A".
2. GEOTEXTILE FABRIC IS NOT REQUIRED OVER AREAS WHERE RIPRAP ALREADY EXISTS. EXISTING RIPRAP IS TO BE IMPROVED TO MATCH THE 2 1/2:1 REQUIRED SLOPE.
3. USE BORROW MATERIAL BEGINNING AT STA. 1+80.00.
4. AUG 2016 SCOUR HOLE WAS NOT INCLUDED IN THE ORIGINAL SURVEY. DIMENSIONS OF SCOUR HOLE WERE OBTAINED FROM FIELD INSPECTION. SEE SHEET 102.
5. BRIDGE IS NOT SHOWN FOR CLARITY.
6. SEE LANDSCAPING NOTE ON GENERAL NOTES SHEET 101 FOR MORE INFORMATION ON JOINT PLANTING.

LEGEND

- ▨ RIPRAP (440 LB)
- ▨ GEOTEXTILE FABRIC
- ▨ BORROW


SCALE: 1/8" = 1'



DETAIL "A"
TOE OF SLOPE (N.T.S.)



SHEET NUMBER		104
PROJECT		LA 10. AMITE RIVER SCOUR REPAIR
DATE		11/03/16
BY		S. C.
CHECKED		S. C.
DESIGNED		S. C.
REVIEWED		S. C.
APPROVED		S. C.
STATION		061-07
SECTION		061-07
PROJECT		H.O.1934
DRAWN BY		S. C.
CHECKED BY		S. C.
DESIGNED BY		S. C.
REVIEWED BY		S. C.
APPROVED BY		S. C.
ST. HELENA		
BRIDGE & STRUCTURAL DESIGN		



NOTES

1. RIPRAP (440 LB) TO BE PLACED AS SHOWN. SEE SHEETS 103 AND 104 FOR ADDITIONAL INFORMATION.
2. FOR DETAILS ON THE PROJECTED AND ADOPTED ALIGNMENT FOR WEST BANK OF AMITE RIVER SEE SHEET 103.
3. STONE RIPRAP (440 LB) SHALL BE USED. RECYCLED CONCRETE SHALL NOT BE USED.
4. FILL MATERIAL SHALL BE PAID FOR UNDER ITEM 203-07-0100 (BORROW - VEHICULAR MEASUREMENT).

																																																																																																																																																																									
--	--	---	--	---	--	---	--	---	--	---	--	---	--	--	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--











LA 10 Amite River

Construction Photos



LA 10 Amite River

Construction Photos



Line Number	Item Number	Item Description	Quantity	Unit of Measure	- 1 - Barriere Construction Co., LLC.		- 2 - Palmisan Construction LLC							
					Unit Price	Total Amount	Unit Price	Total Amount						
0001	202-02-32120	Removal of Pipe (Side Drain) 15" DIA RCP	22	LNFT	25.00	550.00	0.01	0						
0002	203-07-00100	Borrow (Vehicular Measurement)	4,860	CUYD	30.00	145,800.00	40.00	194,400						
0003	401-02-00100	Aggregate Surface Course (Adjusted Vehicular Measurement)	94.7	CUYD	30.00	2,841.00	50.00	4,735						
0004	701-05-01040	Side Drain Pipe (18" RCP/PP/CMP)	26	LNFT	70.00	1,820.00	105.00	2,730						
0005	711-03-00700	Riprap (440 lb)	20,512.5	TON	61.00	1,251,262.50	58.00	1,189,500						
0006	711-04-00100	Geotextile Fabric	8,757	SQYD	1.00	8,757.00	0.50	4,378.50						
0007	713-01-00100	Temporary Signs and Barricades	1	LUMP	20,000.00	20,000.00	25,000.00	25,000.00						
0008	726-01-00100	Bedding Material	2.5	CUYD	250.00	625.00	1.00	2.50	305.00	762.50	90.00	225.00		
0009	727-01-00100	Mobilization	1	LUMP	20,000.00	20,000.00	120,000.00	120,000.00	85,600.00	85,600.00	67,255.00	67,255.00		
0010	740-01-00100	Construction Layout	1	LUMP	7,000.00	7,000.00	36,000.00	36,000.00	12,000.00	12,000.00	3,500.00	3,500.00		
0011	719-04-00100	Landscaping	1	LUMP	20,000.00	20,000.00	21,000.00	21,000.00	23,200.00	23,200.00	28,150.00	28,150.00		
		CONTRACTOR TOTAL				1,478,655.50		1,597,971.22		1,945,399.00		1,965,850.96		

Low bidder, selected pay items

Borrow, 4860 cu.yds.(4)= \$145,800

Mobilization \$20,000

Riprap- 20513 tons (440 lb), \$1,251,253

Geotextile fabric, 8800sqyds \$8,800

Landscaping \$20,000

Total \$1,478,655

Questions?



